



**Technical Service
BULLETIN**


March 24, 2005

Title:

FUEL INJECTOR "TICKING" NOISE

Models:

'01 – '05 Highlander (V6)



ENGINE
REVISÉD
EG013-05

TSB REVISION NOTICE:

- **June 28, 2005:** A new section, "Component Identification," has been added; a note has been added to step 2 of the Repair Procedure, and component identification information has been enhanced in Figures 2 and 6.

The previous TSB should be discarded.

Introduction Some customers with 2001 – 2005 model year Highlander vehicles with V6 engines may complain of a "ticking" noise from the engine compartment when the engine is idling. An updated fuel main tube has been made available, and a second fuel pressure pulsation damper has been added to improve this condition.

- Applicable Vehicles**
- **2001 – 2005** model year **Highlander** vehicles equipped with **V6 engines** produced **BEFORE** the Production Change Effective VINs shown below.

Production Change Information

MODEL	DRIVETRAIN	PRODUCTION CHANGE EFFECTIVE VIN
2005 Highlander	2WD	JTE*P21A#50058820
	4WD	JTE*P21A#50091261

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
EG5015	R & R Fuel Pipe Sub-assembly No. 1	1.0	23801-20180 23801-20120	06	50

Applicable Warranty*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
23801-20180 23801-20120	23801-20260	Pipe Sub-assembly, Fuel, No. 1	1
23270-62010	23270-62011	Damper Assembly, Fuel Pressure Pulsation	1
23232-41081	Same	Gasket	4

Required SSTs

ITEM NO.	SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QTY	DRW**
1	Toyota Diagnostic Tester Kit* NOTE: • All components from this kit/set are required • 12 Megabyte Diagnostic Tester Program Card (P/N 01002593-005) with version 12.2a Software (or later) is required	TOY220036	1	9
2	CAN Interface Module Kit* NOTE: • All components from this kit/set are required	01002744	1	9


* Essential SSTs.

** Refers to drawer number in SST Storage System.

NOTE:
 Additional Diagnostic Tester Kits, CAN Interface Modules, Program Cards, or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.


Component Identification

Bolt and 2 Washers



BOLT AND 2 WASHERS ARE REMOVED AND REPLACED WITH NEW PULSATION DAMPER AND GASKET

Pulsation Damper and Gasket



NEW PULSATION DAMPER AND GASKET INSTALLED WHERE BOLT AND WASHERS WERE REMOVED

Repair Procedure

CAUTION:

- Do NOT smoke or work near an open flame when working on the fuel system.
- Keep gasoline away from rubber or leather parts.
- Wear safety goggles while working with the fuel system under pressure.
- Do NOT disconnect any part of the fuel system until you have discharged the fuel system pressure.
- Even after discharging the fuel pressure, place a shop rag over fittings as you separate them to reduce risk of fuel spray on yourself or in the engine compartment.

1. Discharge fuel system pressure.
 - A. Remove Circuit Opening Relay from Relay Block No. 1 located to the left of the Instrument Panel Junction Block behind the left lower finish panel.




Figure 1


- B. Start the engine. After the engine has stalled, turn the ignition switch OFF.
- C. Reinstall the Circuit Opening Relay.
- D. Disconnect the negative (-) battery cable.

Repair Procedure
(Continued)


2. Disconnect Fuel Pipe Sub-assembly No. 1.

NOTE:

- Ensure that the removed bolt and washers are discarded.
- Refer to the "Component Identification" section on page 2 to ensure that the correct bolt and washers are removed and damper is installed.






- A. Disconnect the fuel pipe clamp No. 1 from the connector.
- B. Check if there is any dirt or mud on the pipe and around the connector before disconnecting the fuel line. Clean if necessary.



Repair Procedure
(Continued)

- C. Disconnect the connector from the hose while pinching portion "A" with your fingers as shown in the illustration.
- D. If the connector and pipe are stuck, pinch the fuel pipe, push and pull the connector by hand to disconnect them. Do not use any tools.
- E. Drain the fuel that remains inside Fuel Pipe Sub-assembly No. 1.
- F. Place a tray under the vehicle or point of disconnection, if needed, to catch any fuel that may spill.
- G. Protect the disconnected fuel lines from debris by covering with a vinyl or plastic bag.
- H. Remove the original pulsation damper from the rear fuel rail.
- I. Remove and discard the remaining bolt holding Fuel Pipe Sub-assembly No. 1 to the front fuel rail.



- 3. Install the new Fuel Pipe Sub-assembly No. 1 onto the vehicle.
- 4. Install both the original pulsation damper and the new (additional) damper with the new fuel pipe hose gaskets as shown, and torque to the following specifications.
Torque: 33 N•m (24 ft•lbf, 331 kgf•cm)

**Repair
Procedure**
(Continued)

5. Check for fuel leaks.
 - A. Reconnect the negative (–) battery terminal.
 - B. Connect the Toyota Diagnostic Tester.
 - C. Turn the ignition switch to the “ON” position (do NOT start the engine).
 - D. Turn the Diagnostic Tester ON.
 - E. Select “1. DIAGNOSIS” on the Diagnostic Tester.
 - F. Select “2. ENHANCED OBD II.”
 - G. Select “3. ACTIVE TEST.”
 - H. Select “FUEL PUMP/SPD.”
 - I. Turn on the fuel pump with Active Test by pressing the right arrow on the Diagnostic Tester.
 - J. Check for fuel leaks.
 - K. Check and clear any DTCs that may have been set while performing the repair.
6. Once confirmed that no leaks are present, take the vehicle on a test drive to ensure that any air trapped in the pulsation dampers has been purged.
7. Repair is complete.