


**TSB REVISION NOTICE:**

- **March 2, 2007: The T1 code in the Warranty Information table has been updated. Previous versions of this TSB should be discarded.**

**Introduction** On some vehicles, when Rapgard™ is removed, the paint may have a stained appearance. These stains appear to be under the clear coat and should not be considered a defect in the paint (clear coat or color coat). The stain patterns are usually under wrinkles in the Rapgard™. These wrinkles sometimes trap water and cause the paint to stain from the trapped moisture, especially on horizontal surfaces, such as the hood, roof, and trunk. Stains can be removed by heating the stained surface to remove the trapped moisture.



- Applicable Vehicles**
- **2007** model year **Toyota** and **Scion** vehicles.

**Warranty Information**

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
BD6004	Remove Paint Stain Under Rapgard™	0.6	53301-#####	99	99

**Applicable Warranty\*:**

**This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.**

\* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

Required Tools & Material	TOOLS & MATERIALS	QUANTITY
	Infrared Lamp or Heat Gun	1
	Aluminum Foil or Damp Cloth	1
	Thermometer	1

**Repair  
Procedure**

1. Use the aluminum foil or damp cloth to cover plastic/rubber parts that are near the stain.
2. Apply heat to the stain using an infrared lamp or heat gun.

**NOTE:**

**Apply heat for 5 – 10 minutes at 158°F – 176°F (70°C – 80°C). Do NOT allow the surface to become hotter than 176°F (80°C). Measure the temperature with a thermometer.**

3. After applying heat for 5 minutes, examine the area to determine if the stain has been removed. If the stain still exists, continue to apply heat and re-examine the stain 5 minutes later.