

TOYOTA

SERVICE BULLETIN

TOYOTA MOTOR SALES, U.S.A., INC.

VOLUME

10

REFERENCE AUDIO
NUMBER 001
DATE 12-23-88
MODEL ALL MODELS

Page 1 of 1

DIGITAL DISPLAY ILLUMINATION '89 MODEL YEAR RADIO

- SYMPTOM:** No illumination on radio chassis P/N 08600-00823 model 6633 when headlights are turned ON.
- CAUSE:** The six pin connector has not been installed. (Please refer to illustration below).
- CORRECTION:** Connect the six pin connector.

