



**Technical Service
BULLETIN**

March 27, 1998

Title:
**CUPHOLDER PERFORMANCE
IMPROVEMENT**

Models:
'98 Avalon

TFSB

BODY
BO006-98

Introduction Production changes have been implemented to improve the performance and function of the console mounted cupholder on 1998 Avalon vehicles. In some cases, customers may be concerned by a sticking/slow operating cupholder.

Production Change Information

- **1998 Avalon** vehicles starting with VIN **4T1BF18B * WU225657**.

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME
55620-AC010-XX	Same	Holder Assembly, Instrument Panel Cup

NOTE:
Countermeasured parts can be identified by the absence of "Guide Tabs", which were located on the front edges of the cupholder.



OP CODE	DESCRIPTION	TIME	OPN	T1	T2
550601	R&R Instrument Panel Cupholder Assembly	0.3	55620-AC010-XX	54	83

Applicable Warranty*:
This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

Repair Procedure 1998 Avalons built prior to the starting VIN listed that exhibit a sticking/slow operating cupholder may be repaired by replacing the cupholder assembly.

