



**Technical Service
BULLETIN**

May 31, 2002

Title:

JBL AUDIO SYSTEM POP NOISE

Models:

'02 Camry



AUDIO
AU002-02

Introduction A new JBL amplifier has been designed for the 2002 model year Camry to address customer complaints of a pop noise occurring while turning off the ignition key.

- Applicable Vehicles**
- **2002** model year **Camry** vehicles **equipped with the JBL audio system.**

**Production
Change
Information**

MODEL	ENGINE	ORIGIN	STARTING VIN
Camry	4 cylinder	NAP	4T1BE3#K#2U <u>Q</u> 22882*
			4T1BE3#K#2U <u>5</u> 24790*
	6 cylinder		4T1BF3#K#2U <u>Q</u> 12303*
			4T1BF3#K#2U <u>5</u> 13386*
	4 cylinder	Japan	JTDBE3#K#20067500
			JTDBF3#K#20036565
6 cylinder			

* Underlined number in VIN represents assembly plant line code.

**Parts
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
86280-AA070 86280-AA071	86280-AA072	JBL Amplifier	1

Repair Procedure Order a replacement amplifier through the JBL exchange program by calling 1-800-456-4265.

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
860601	R & R Amplifier Assembly, Stereo	0.3	86280-AA070 86280-AA071	91	71

Applicable Warranty*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

