



**Technical Service
BULLETIN**

March 8, 2006

Title:
FOG LAMPS LOOSE
Models:
'05 – '06 Avalon

T S B

**BODY
B0007-06**

Introduction Some 2005 – 2006 model year Avalon customers may complain that the fog lamps are loose. The fog lamp brackets and bumper hole covers have been modified to correct this condition.

- Applicable Vehicles**
- **2005 – 2006** model year **Avalon** vehicles produced **BEFORE** the Production Change Effective VIN shown below.

**Production
Change
Information**

MODEL	PRODUCTION CHANGE EFFECTIVE VIN
Avalon	4T1BK36B#6U095437

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
BD5026	R & R Fog Light Assembly (One Side)	0.6	81620-AC020	62	57
Combo A	Opposite Side	0.6			

Applicable Warranty*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



**Parts
Information****Vehicles without Laser Cruise Control:**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
81219-AC010	Same	Bracket, Fog Lamp, RH	1
81229-AC010	Same	Bracket, Fog Lamp, LH	1
81610-AC020	Same	Assembly, Cover, RH	1
81620-AC020	Same	Assembly, Cover, LH	1
90468-04059	Same	Clip	6

Vehicles with Laser Cruise Control:

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
81219-AC010	Same	Bracket, Fog Lamp, RH	1
81229-AC010	Same	Bracket, Fog Lamp, LH	1
81620-AC020	Same	Assembly, Cover, LH	1
90468-04059	Same	Clip	4

**Repair
Procedure**

Replace fog lamp brackets and bumper hole covers.

Refer to the Technical Information System (TIS), 2005 or 2006 model year Avalon Repair Manual: *Lighting: Fog Lamp Assy LH: Overhaul.*