



Technical Service BULLETIN

June 9, 2003

Title:

CLOCK RESETS TO 12:00

Models:

'03 Matrix

T S B

AUDIO
AU002-03

Introduction Some customers may experience the clock in the radio resetting to 12:00 when starting the engine with several electrical devices on (headlights, blower, etc.). An improved radio is available to address this condition.

Applicable Vehicles

- **2003** model year **Matrix** vehicles **equipped with the single disc CD player.** Radio faceplate model numbers affected are **AD1800** and **AD6808** on vehicles produced **BEFORE** the Production Change Effective VIN shown below.

Production Change Information

MODEL	PRODUCTION CHANGE EFFECTIVE VIN
Matrix	2T1KR32E#3C756961

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
86120-02330	Same	Radio with CD Player	1
86120-02340		Radio with CD Player and Cassette	1

Repair Procedure

Order a replacement radio through the Delphi Exchange Program (AER) by calling 1-800-321-6970.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
860451	R & R CD Player Assembly	0.3	86120-02330 86120-02340	87	99

Applicable Warranty*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

