



**Technical Service
BULLETIN**

September 21, 2004

Title:

**POWER/RADIO WIRE HARNESS FOR
REAR SEAT ENTERTAINMENT SYSTEM**

Models:

'04 Land Cruiser

AX005-04
ACCESSORIES

Introduction For the Rear Seat Entertainment system for Land Cruiser vehicles (P/N PT296-6002D), the current Power/Radio Wire Harness has a missing wire that inhibits the radio beep sound when using the Toyota Navigation system.

- Applicable Vehicles**
- **2004** model year **Land Cruiser** vehicles equipped with **Rear Seat Entertainment** and **Toyota Navigation** systems.

**Parts
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
PT296-60024-W4	PT296-60024-W5	Rear Seat Entertainment Power/Radio Wire Harness	1

**Repair
Procedure**

To correct this problem, replace the current Power/Radio wire harness with the new part, P/N PT296-60024-W5. Please refer to the Technical Information System (TIS), applicable model year Land Cruiser: *Accessories: Diagnostic Guides*.

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
ZT6806	R & R Power/Radio Wire Harness	1.0	PT296-60024-W4	72	41

Applicable Warranty*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

