



**Technical Service
BULLETIN**

April 3, 1998

Title:
**REAR WIND DEFLECTOR
INSTALLATION NOTE**

Models:
'98 Land Cruiser

ACCESSORY
AX001-98

Introduction This bulletin is a correction to the installation instructions for the Land Cruiser Rear Wind Deflector, page 2, step 7 which states "Make sure the front edge of the Template is in contour with the front edge of the door."

Affected Vehicles


- 1998 model year Land Cruiser

Parts Information

OLD PART NUMBER	NEW PART NUMBER	PART NAME
N/A	PT221-60980	Rear Wind Deflector

Change to Procedure Page 2, step 7 of the installation instructions *should* state: "Make sure the black printed line on the template lines up with the front edge of the door."

NOTE:
Do not line up edge of plastic template to edge of door.



Warranty Information

OP CODE	NWC	DESCRIPTION	TIME	OPN	T1	T2
Not Applicable to Warranty						

