



**Technical Service  
BULLETIN**

January 25, 2005

Title:  
**SUNROOF WIND DEFLECTOR  
GASKET FIT**

Models:  
**'04 – '05 Land Cruiser**

**AX002-05  
ACCESSORIES**

**Introduction** Some 2004 and 2005 model year Land Cruiser vehicles may have a gap between the sunroof wind deflector gasket and the roof panel. Please use the following repair procedure to correct this fit-up issue.

- Applicable Vehicles**
- **2004 – 2005** model year **Land Cruiser** vehicles.

**Parts  
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
PT415-60030	PT415-60040	Sunroof Wind Deflector	1
–	PT415-60040-HK	Hardware Kit	1

**Repair  
Procedure**

The sunroof wind deflector, P/N PT415-60030, should be installed according to the instructions included with the part. If necessary, a copy of the current installation instructions can be found on the Technical Information System (TIS) under Accessories, Installation Instructions. If a proper fit cannot be obtained (i.e., there is a gap between sunroof wind deflector gasket and roof panel), replace screws and brackets with those in the hardware kit, P/N PT415-60040-HK.

Sunroof wind deflector P/N PT415-60030 will be superseded by P/N PT415-60040 once P/N PT415-60030 inventory has been depleted.

**Warranty  
Information**

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
ZT1511	R & R Sunroof Wind Deflector	0.2	PT415-60030	59	43

**Applicable Warranty\*:**

**This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.**

\* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

