



**Technical Service
BULLETIN**

November 30, 2001

Title:

WIND NOISE AT "A" PILLAR

Models:

'01 Highlander



NVH
NV012-01

Introduction Improvements have been made to the front door weatherstrip in order to minimize wind noise on the 2001 model year Highlander.

- Applicable Vehicles**
- **2001** model year **Highlander** vehicles.

**Production
Change
Information**

MODEL	STARTING VIN
Highlander (6 Cylinder) 4WD-MCU25L	JTEHF21A610032677
Highlander (6 Cylinder) 2WD-MCU20L	JTEGF21AX10023377
Highlander (4 Cylinder) 4WD-ACU25L	JTEHD21A910009089
Highlander (4 Cylinder) 4WD-ACU20L	JTEGD21A210016672

**Parts
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
67861-48020	67861-48021	Front Door Weatherstrip, RH	1
67862-48020	67862-48021	Front Door Weatherstrip, LH	1

**Repair
Procedure**

Remove the front door weatherstrip and install new part if applicable VIN.

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
671351	R & R Front Door Weatherstrip	0.2	6786#-48020	91	99
Combo A	Opposite Side	0.1			

Applicable Warranty*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

