



**Technical Service
BULLETIN**

December 4, 1998

Title: **WOOD APPLIQUE KIT CHANGE**

Models:
'98 Land Cruiser

T S B

**ACCESSORY
AX004-98**


Introduction Due to variation in vehicle build tolerance the Shift Console Storage Door Fascia piece (Service P/N PT613-60985-CR) sometimes contacts the console when open. This causes a mark on the Shift Console Storage Door Fascia piece.

- Affected Vehicles**
- **1998** model year **Land Cruiser** with optional **Wood Applique Kit** installed.

Part Number Information

ORIGINAL PART NUMBER	CURRENT PART NUMBER	PART NAME
PT613-60980	same	Wood Applique Kit

Part Change Information



Repair Procedure Do not install the Shift Console Storage Door Fascia piece. This part will not be warrantable. Install Wood Kit as instructed with exception of this part.

Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-

