



# TECHNICAL SERVICE BULLETIN

**REF.:** ACCESSORIES  
**NO.:** AX93-004  
**DATE:** DECEMBER 17, 1993  
**MODEL:** 4RUNNER (RN/VN)


## 1994 M/Y 4RUNNER RUNNING BOARDS

Page 1 of 1

To insure proper fit and prevent poor appearance, it is extremely important that technicians follow the installation instructions closely during running board installation. Pay particular attention to mating surfaces of:

- Running board platform to end cap
- Endcap to vehicle rocker

See illustration below for indicated locations.



### **RUNNING BOARD ADJUSTMENT PROCEDURE:**

To obtain the best possible fit, adjust the running board platform vertically (up and down) and horizontally (inboard and outboard of the vehicle). Confirm that the rubber gasket forms a tight and secure seal between the endcap and vehicle rocker.

TOYOTA MOTOR SALES U.S.A., INC.