



# TECHNICAL SERVICE BULLETIN

**REF.:** AUDIO  
**NO.:** AU001-96  
**DATE:** JANUARY 26, 1996  
**MODEL:** AVL

## '95 AVALON DELCO RADIO FM HIGH PITCHED TONE

Page 1 of 2

The '95 Avalon Delco radio models AD1700 and AD6800 have been modified to improve the following condition:

While listening to low frequency FM stations (87.9 ~ 99.9 MHz), a high pitched tone may be heard.

### VEHICLE PRODUCTION EFFECTIVE:

4T1GB1XXSU016502

### PART NUMBER INFORMATION:

PART NUMBER	MODEL NUMBER	DESCRIPTION
86120-AC020	AD1700	Premium Combo
86120-AC030	AD6800	Premium Combo with CD Controller

### EXCHANGE INFORMATION:

Delco began shipping countermeasured exchange units starting February 1995. Countermeasured AD1700 radios have an "A" on the service label. Countermeasured AD6800 radios have a "BR" on the service label.

Radio Model AD1700	Radio Model AD6800
<p>SVC * : 16186349            REM * :            SERIAL: 1049191            FACTORY AUTHORIZED REMANUFACTURED            MODULE FOR DELCO ELECTRONICS CORP            MADE IN MEXICO            UR100444621</p>	<p>SVC * : 16186349            REM * :            SERIAL: 1049191            FACTORY AUTHORIZED REMANUFACTURED            MODULE FOR DELCO ELECTRONICS CORP            MADE IN MEXICO            UR100444621</p>

**NOTE:** Exchange radios can be ordered through United Radio.  
 Telephone: 1 (800) 448-0944 Fax: 1 (800) 701-3874

**WARRANTY INFORMATION:**

OPCODE	DESCRIPTION	TIME	OPN	T1	T2
860031	Radio Tuner Assembly R&R	0.3	86120-AC0X0	76	73

