

REF.: PRODUCT GENERAL INFORMATION
 NO.: PG95-001
 DATE: JANUARY 1, 1995
 MODEL: ALL MODELS


1995 TECHNICAL SERVICE BULLETIN AND BINDERS

Page 1 of 1

For 1995 Technical Service Bulletins, a newly designed and reinforced "D-ring" TSB binder will be sent to your dealership in February. The new binder will also be provided to all currently registered Master Diagnostic Technicians and all Master Technicians.

Use the following steps to ensure a smooth transition from 1994 to 1995 bulletins:

- All 1994 Technical Service Bulletins should be relocated to a temporary binder.
- Place this bulletin along with all 1995 bulletins into the emptied TSB binder.
- In February, all dealers will receive the new TSB binder & tabs for 1995 service bulletins. Please do not order additional binders except for replacement use.
- During the month of March, all dealers will receive bound books containing all TSB's issued in 1994. Upon receipt, discard all 1994 bulletins and refer only to the bound books.
- Additional copies of 1995 TSB's are available to all Toyota dealerships through the Toyota Non-Parts System (MDC NPM system) by using the following part number example:



RELATED TSB PART NUMBERS :

MATERIAL DESCRIPTION	PART NUMBER
1995 TSB Binder Complete With All Bulletins Issued To Date:	TSB95★
New TSB Binder and Tabs Only:	00406-61012★
1994 TSB Bound Book:	00401-43037★
1993 TSB Bound Book:	00401-43014

★ Available in March, 1995

If you have any questions concerning Toyota Service Bulletins, please contact your District Service Manager.