

# A750E Transmission Extension Housing Seal Service Tip

**Service Category** Drivetrain

**Section** Automatic Transmission/Transaxle

**Market** USA

Toyota Supports  
 ASE Certification 

## Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2003 – 2008	4Runner	Engine(s): 2UZ, 1GR Transmission(s): 5AT VDS(s): ZT14R, ZT17R, ZU14R, ZU17R
2007 – 2008	FJ Cruiser	Engine(s): 1GR Transmission(s): 5AT VDS(s): ZU11F
2005 – 2008	Sequoia	Transmission(s): 5AT VDS(s): ZT34A, ZT38A, ZT64A, ZT68A
2005 – 2009	Tacoma	Engine(s): 1GR Transmission(s): 5AT VDS(s): JU62N, KU72N, TU62N
2005 – 2008	Tundra	Engine(s): 2UZ, 1GR Transmission(s): 5AT VDS(s): ET341, ET381, ET541, ET581, JT321, JT521, JU321, JU521, LT521, LU521, RT341, RT381, RT541, RT581, RU341, RU541, ST541

## Introduction

The extension housing oil seal for the 2WD A750E (5-speed rear wheel drive) automatic transmission has been changed in production to a double-lip seal.

Use the current part number in this bulletin anytime the extension housing oil seal is replaced on all 2WD A750E transmissions.

## Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–

## A750E Transmission Extension Housing Seal Service Tip

---

### Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
90311-40001	90311-40034	Seal, Type T Oil	1

**NOTE**

The previous oil seal part number (90311-40001) is still available as a service part since this seal is used on other components.