



**Technical Service
BULLETIN**

March 22, 2002

Title: **ACCESSORY TRAILER WIRE HARNESS**

Models:
'02 Highlander

AX002-02
ACCESSORIES


Introduction There is a part update for the 2002 model year Highlander with factory Tow Prep Package using the Accessory Towing Receiver Hitch and Wire Harness Kit. Future kits will incorporate a 20 amp fuse, for your convenience, which is required to complete the installation.

- Applicable Vehicles**
- **2002** model year **Highlander with factory Tow Prep Package** using the **Accessory Towing Receiver Hitch** option.

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
PT228-69020	PT228-69025	Towing Receiver Hitch	1
08921-48040	08921-48041	Trailer Hitch Converter Kit	1

Repair Procedure Install a 20A fuse (P/N 90982-09011) into the Engine Room Relay Block as shown.



Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-

