



TECHNICAL SERVICE BULLETIN

REF.: ACCESSORIES

NO.: AX93-001

DATE: JUNE 4, 1993

MODEL: ALL MODELS


BATTERY REPLACEMENT IN REMOTE TRANSMITTERS

Page 1 of 1

Some vehicles equipped with the Toyota Vehicle Security System (TVSS) may experience an inoperative remote transmitter due to the battery being run down.

The remote transmitter battery may be replaced as follows: **(see picture below)**

- Remove the two screws on the back of the remote transmitter.
- Remove the old battery.
- Correctly place the new battery in the remote transmitter, positive side up.
- Re-install the screws.



PART NUMBER INFORMATION:

Remote Transmitter Part Number: 00398-00923
Battery Part Number: 08192-00840

TOYOTA MOTOR SALES U.S.A., INC.