

TOYOTA

SERVICE BULLETIN

TOYOTA MOTOR SALES, U.S.A., INC.

VOLUME

9


REFERENCE AUDIO
NUMBER 006
DATE 07-01-88
MODEL ALL MODELS

Page 1 of 1

CASSETTE TAPE REMOVAL WHEN NO-EJECT CONDITION EXISTS

In the event of a cassette tape not ejecting from the tape deck, **do not disassemble cassette deck to remove the tape.** Improper disassembly procedures could result in damage to the cassette deck and customer's cassette tape.

Please send the cassette deck chassis to an authorized service facility. The cassette tape will then be removed at the service center and mailed directly to the customer.



PLEASE ATTACH THE CUSTOMER'S NAME AND ADDRESS TO THE RADIO/PLAYER WARRANTY CLAIM FORM.