




# TECHNICAL SERVICE BULLETIN

REF.: BODY  
 NO.: BO94-010  
 DATE: JULY 15, 1994  
 MODEL: SW

## CLIP FOR RADIATOR SUPPORT UPPER SEAL

Page 1 of 2

The quantity of clips used to attach the radiator support upper seal has been changed from 7 clips to 2, as shown below. In addition, 3 plug plates have been installed at location "1" holes.



	Location 1	Location 2	Location 3
Previous	Clip x 3	Clip X 2	Clip X 2
New	Plug Plate X 3	None	Clip X 2

**PRODUCTION EFFECTIVE:**

<b>From Vin #</b>	<b>P/D</b>
JT2SW21N5R0021316	November, 1993
JT2SW22N5R0087394	November, 1993

**PART NUMBER INFORMATION:**

<b>Part Name</b>	<b>Previous Part #</b>	<b>New Part #</b>	<b>Quantity</b>
Clip	90467-07072-01	Same	2
Plug Plate	None	90333-25001	3