



**Technical Service  
BULLETIN**

June 25, 1999

Title:

**DELAYED UPSHIFT TO OVERDRIVE  
WITH CRUISE CONTROL ENGAGED**

Models:

'98 4Runner 3RZ-FE

**ELECTRICAL  
EL004-99**

**Introduction** Under certain conditions, a delayed upshift to O/D after cresting a hill with Cruise Control engaged may be felt in some 4Runners. To improve shift timing, the Cruise Control ECU Logic has been changed.

- Affected Vehicles**
- All 1998 MY 4 Cylinder (3RZ-FE) 2WD and 4WD 4Runners equipped with Automatic Transmissions.

**Parts  
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME
88240-35290	88240-35291	Computer Assembly, Cruise Control

**Warranty  
Information**

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
887021	R & R Cruise Control ECU	0.3	88240-35290	43	71

**Applicable Warranty\*:**

**This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.**

\* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

