



**Technical Service
BULLETIN**

May 25, 2001

Title:

**EXCESSIVE BASS
(BOOMY BASS, JBL AMPLIFIER)**

Models:

'01 Land Cruiser

Audio
AU001-01

Introduction A new JBL amplifier has been designed for the 2001 model year Land Cruiser to address customer concerns regarding too much bass and/or the inability to reduce the bass output level in the sound system.

- Applicable Vehicles**
- 2001 model year **Land Cruiser** vehicles.

**Production
Change
Information**

MODEL	STARTING VIN
Land Cruiser	JTEHT05J#12009229

**Parts
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME
86280-0W060	Same	JBL Amplifier

NOTE:

Revised parts will show a “-C” after the part number on the parts label.

**Repair
Procedure**

Order a replacement unit through the JBL exchange program by calling 1-800-456-4265.

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
860601	R & R Amplifier	0.3	86280-0W060	76	99

Applicable Warranty*:

This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle’s in-service date.

* Warranty application is limited to correction of a problem based upon a customer’s specific complaint.

