



TECHNICAL SERVICE BULLETIN


REF.: HEATING & AIR
CONDITIONING
NO.: AC95-002
DATE: JUNE 16, 1995
MODEL: AE

HEATER CONTROL KNOB RETENTION IMPROVEMENT

Page 1 of 1

To improve retention of the Heater Control Knobs on North American built Corollas, a production change has been made. The inner dimension of the knob has been modified to provide an audible "click" when installed properly.

ILLUSTRATION:



PRODUCTION EFFECTIVE:

VIN	Date	Plant
1NXAE0—SZ254159	11/94	NUMMI
2T1AE09B7SC102771	11/94	TMMC
2T1AE04B9SC078268	11/94	TMMC

PART NUMBER INFORMATION:

Previous Part Number	New Part Number	Part Name
55905-02050	55905-02011	Knob, Heater Control (Upper)
55905-02060	55905-02021	Knob, Heater Control (Lower)

INTERCHANGEABILITY:

New Heater Control Knobs are interchangeable with previous vehicles.