



**Technical Service
BULLETIN**

March 1, 2004

Title:

INSTALLATION INSTRUCTION CHANGE

Models:

'04 Highlander



ACCESSORIES
AX002-04

Introduction The Toyota accessory, Auto Dimming Mirror (PT374-48020), installation instructions describes a T-tap connector to the red-blue wire, pin #3 in connector IB2. The factory made a running change to the color of the wire from red-blue to yellow. The connector and pin number location are unchanged.

- Applicable Vehicles**
- 2004 model year **Highlander** vehicles equipped with 2AZ-FE and 3MZ-FE engines.


Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME
N/A	PT374-48020	Auto Dimming Mirror

Repair Procedure

Reference the EC Mirror installation instructions (PT374-48020):

1. Change paragraph E8ii from "Locate the red-blue, pin #3, in connector IB2" to read "Locate the YELLOW wire, pin #3, in connector IB2."
2. Change paragraph E9 from "Apply the red T-tap connector to the Red-Blue wire to read "Apply the red T-tap connector to the YELLOW wire."



Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-

