



Technical Service
BULLETIN

May 2, 1997

Title:

MIL 'ON' – P0116 SET IN MEMORY (ECM)

Models:

'97 Land Cruiser



ENGINE
EG003-97

Introduction

Some 1997 Land Cruisers may exhibit a MIL "ON" condition (DTC code P0116 – "engine coolant temperature malfunction") under certain normal operating conditions. To improve the operating logic of the coolant temperature circuit, the engine ECM has been changed.

NOTE:

When diagnosing a vehicle with this condition, check all related components according to the Repair Manual. If all parts pass testing, the ECM logic may be too sensitive and require replacement.

**Production
Change
Information**

- The new ECM was installed in production after **VIN JT3HJ85 * * V0169421**.

**Parts
Information**

PREVIOUS PART NUMBERS	NEW PART NUMBER	PART NAME
89661-60650	89661-60652	Module, Engine Control
89661-60651		

