



# Technical Service BULLETIN

June 28, 2006

Title:

## POOR SOUND QUALITY FROM SATELLITE RADIO

Models:

'07 FJ Cruiser

Audio  
AU002-06


**Introduction** Some customers may experience poor sound quality from the Toyota XM® or SIRIUS® satellite radio accessory option (sound quality is normal in AM, FM, and CD mode). A revised radio has been developed to remedy this condition.

- Applicable Vehicles**
- **2007** model year **FJ Cruiser** vehicles equipped with the upgraded radio and the port or dealer-installed Toyota satellite radio kit (XM® or SIRIUS®).

### Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
86120-35380	Same	Radio Receiver	1

### Required SSTs

ITEM NO.	SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QTY	DRW**
1	Plastic Pry Tool Set*	00002-06000-01	1	20
COMPONENT(S) OF KIT/SET	<p>One (1) component from this kit/set is required:</p> <ul style="list-style-type: none"> <li>• Plastic Panel Clip Removal Tool (P/N 00002-06001-01)</li> </ul> 			

\* Essential SSTs.

\*\* Refers to drawer number in SST Storage System.

**NOTE:**

Additional SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

### Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
860031	R & R Radio Assembly	0.3	86120-35380	85	74

**Applicable Warranty\*:**

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

\* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



**Repair  
Procedure**

1. Order a replacement radio through the Fujitsu-Ten exchange program (refer to the Warranty Policy Handbook for contact information).
2. Replace the radio receiver.  
Refer to the Technical Information System (TIS), 2007 model year FJ Cruiser Repair Manual: *Audio / Visual: Radio Receiver: Removal, Disassembly, Installation, Reassembly.*