



**Technical Service
BULLETIN**

May 22, 2007

Title:
RADAR SECURITY SYSTEM
Models:
'07 FJ Cruiser



**AX001-07
ACCESSORIES**

Introduction Some FJ Cruiser customers may complain that their alarm activates too easily. Customer concerns can be addressed using the RS3200 Plus with Glass Breakage Sensor (GBS). The GBS option offers the user the ability to adjust the alarm sensitivity.

- Applicable Vehicles**
- **2007** model year **FJ Cruiser** vehicles.

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
08586-36821	08586-36822	VIP Security System, RS3200 Plus	1

Repair Procedure

Remove the radar security system (P/N 08586-36821) from the customer's vehicle and replace it with the alternate security system with the glass breakage sensor, "RS3200 Plus w/Glass Breakage Sensor" (P/N 08586-36822). Refer to the Technical Information System (TIS) for installation instructions.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
AX7002	R & R Security System	1.8	08586-36821	99	99

Applicable Warranty*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

