

TOYOTA

SERVICE BULLETIN

TOYOTA MOTOR SALES, U.S.A., INC.

VOLUME

9

REFERENCE ELECTRICAL

NUMBER 003

DATE 01-08-88

MODEL MX73

Page 1 of 1

RADIO FUSE INSTALLATION AT PDS 1988 - CRESSIDA WITH CD PLAYER

The 1988 MX73 Cressida with the optional CD player will be produced in the late December, 1987. The radio fuse in Junction Block No. 2 has been removed at the factory to reduce static discharge during transportation of the vehicle.

The radio fuse which is located on the back side of the Junction Block No. 2 in the engine compartment, must be reinstalled during PDS.

