



TECHNICAL SERVICE BULLETIN

REF.: BRAKES
NO.: BK91-002
DATE: MAY 17, 1991
MODEL: RN/VN

REAR ABS ECU

Page 1 of 1

To prevent false ABS codes 11 and/or 25 on trucks equipped with rear ABS systems, the power transistor circuit inside the ABS ECU has been changed.

NOTE: Before replacing the ABS ECU, the solenoid and solenoid relay circuits should be inspected for an open or short condition.

PRODUCTION EFFECTIVE: From February 1, 1991

BEGINNING VIN'S WITH PRODUCTION CHANGE

4X2 TRUCK	4X4 TRUCK	4 RUNNER
JT#RN81##M5111266 -M0070581	JT#RN01##M7047761	JT#RN27##M0001409
JT#RN82##M5035964 -M9009170	JT#RN02##M7002235	JT#RN37##M7001922 -M0007969
JT#RN93##M5034477 -M9002114	JT#RN13##M6025947 -M9003232 -M8000530	JT#VN29##M0007184
JT#VN82##M5004186	JT#VN01##M2011446 -M0003111	JT#VN37##M7001274 -M9009386 -M0063018 -M8021805
JT#VN93##M5022113	JT#VN02##M2002022	
JT#VN94##M0023197	JT#VN13##M5054479	

PART NUMBER INFORMATION:

PREV. PART NO.	NEW PART NO.	PART NAME	MODEL
89540-35010	89540-35011	COMPUTER ASSY, SKID CONTROL	RN/VZN 4X4 4-RUN 4X2, 4X4
89540-35020	89540-35021	COMPUTER ASSY, SKID CONTROL	RN/VZN 4X2

NOTE: Previous and new parts are interchangeable.

TOYOTA MOTOR SALES U.S.A., INC.