

# TOYOTA

## SERVICE BULLETIN

TOYOTA MOTOR SALES, U.S.A., INC.

VOLUME

**10**

REFERENCE ELECTRICAL

NUMBER 001


DATE 08-11-89

MODEL MX83

Page 1 of 1


### SUN VISOR VANITY MIRROR WIRE ROUTING

To improve the wire harness routing to the vanity mirror light, the design of the metal joint on the sun visor arm has been changed. The flare at the top of the metal joint of sun visor has been removed as shown below:



Previous

New



#### PRODUCTION CHANGE INFORMATION:

Starting VIN

JT2MX83-0032225

Production Effective

May, 1989

#### PART NUMBER INFORMATION:

The part numbers remain unchanged.

P/N 74320-22630-xx

Left Hand Visor Assembly

P/N 74310-22600-xx

Right Hand Visor Assembly