



**Technical Service
BULLETIN**

April 28, 2000

Title:

WHEEL COVER NOISE

Models:

'00 ECHO

TSB

NV009-00

HAN

Introduction Some wheel covers exhibit “squeaking” or “clicking” noise. In the event that the wheel covers make noise, they need to be replaced by new wheel covers.

- Applicable Vehicles**
- **2000** model year **ECHO** vehicles with wheel cover part number PT255–52000.

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME
PT255–52000	PT255–52001	Wheel Cover, 14” (Set of 4)

Repair Procedure

Remove and replace existing wheel covers (4) with new wheel covers (4).

Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
ZT7111	R & R Wheel Cover – All Wheels	0.2	PT255–52000	91	44

Applicable Warranty*:

This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle’s in-service date.

* Warranty application is limited to correction of a problem based upon a customer’s specific complaint.

