



TECHNICAL SERVICE BULLETIN

REF.: PRODUCT GENERAL
INFORMATION

NO.: PG92-001

DATE: JANUARY 1, 1992

MODEL: ALL MODELS

1992 TECHNICAL SERVICE BULLETIN GENERAL INFORMATION

Page 1 of 1

Toyota Service Bulletins (TSB's) continue to be the most current information available on Toyota products, and Toyota has taken the following steps to help ensure complete access to this reference source:

- ⊕ During the month of March, service personnel will receive a bound book containing all TSB's issued in 1991. Upon receipt of this book, all 1991 bulletins in your TSB binder may be discarded or relocated to an empty binder. The TSB binder should then be used for new 1992 bulletins beginning with this shipment.
- ⊕ When the need arises, additional TSB material can be ordered through the Toyota Non-Parts System by using the following part numbers:

MATERIAL DESCRIPTION	PART NUMBER
1992 TSB Binder Complete with all Bulletins Issued to Date:	TSB92
TSB Binder and Tabs Only:	00406-61012
1991 TSB Bound Book:	00401-42973*
1990 TSB Bound Book:	00401-42936
1989 TSB Bound Book:	00401-42900
1988 TSB Bound Book:	00401-42870
1987 TSB Bound Book:	00401-42844
1991 TSB Microfiche:	00406-61014**
1990 TSB Microfiche:	00406-61013

* Available in March, 1992

** Available in April, 1992

If you have any questions concerning Toyota Service Bulletins, please contact your District Service Manager.

TOYOTA MOTOR SALES U.S.A., INC.