

# TOYOTA TECHNICAL SERVICE BULLETIN

**REF.:** PRODUCT GENERAL INFORMATION

**NO.:** PG94-001

**DATE:** JANUARY 7, 1994


**MODEL:** ALL MODELS

## 1994 TECHNICAL SERVICE BULLETIN GENERAL INFORMATION

Page 1 of 1

Toyota Service Bulletins (TSB's) continue to be one of the most current sources of technical information available. To ensure complete access to this reference source, use the following steps below:

- ⊕ All 1993 TSB material should be relocated to an empty binder.
- ⊕ Place this bulletin along with all 1994 bulletins into the emptied TSB binder.
- ⊕ During the month of March, service personnel will receive a bound book containing all TSB's issued in 1993. This book contains the final revisions for all 1993 TSB's. Upon receipt, discard all other '93 bulletins and refer only to this book.
- ⊕ Additional 1993 & 1994 TSB's are available to all Toyota dealerships through the Toyota Non-Parts System (MDC NPM system) by using the following part number example:



### RELATED TSB PART NUMBERS :

MATERIAL DESCRIPTION	PART NUMBER
1994 TSB Binder Complete With All Bulletins Issued To Date:	TSB94
TSB Binder and Tabs Only:	00406-61012
1993 TSB Bound Book:	00401-43014★
1992 TSB Bound Book:	00401-42991

★ Available in March, 1994

**If you have any questions concerning Toyota Service Bulletins, please contact your District Service Manager.**