

Title:


**'97 PIO/DIO 34224 FUJITSU TEN CD PLAYER DOES NOT EJECT / ACCEPT CD**

Models:

**All '97 Models**

**Introduction**

The PIO/DIO 34224 Fujitsu Ten CD Player's (P/N 08601-00852) circuitry was changed to eliminate "does not eject/accept CD" conditions.



**Production Change Information**

- Production change occurred in February 1997 on CD players starting with serial number A4400001.

**Exchange Unit Information**

- Fujitsu Ten began shipping the countermeasured exchange units starting December 1996.
- Countermeasured CD players have a black dot after the Toyota Parts Number.

