



Technical Service BULLETIN

January 17, 1997

Title:

1997 TECHNICAL SERVICE BULLETINS AND BINDERS

Models:


All Models

PRODUCT GENERAL INFORMATION PG001-97

Introduction

Toyota Technical Service Bulletins (TSBs) continue to be one of the most current sources of technical information available. To ensure complete access to this reference source, use the following steps:

- All 1996 Technical Service Bulletins should be relocated to a temporary binder.
• Place this bulletin along with all 1997 bulletins into the emptied TSB binder.
• During the month of March, all dealers will receive bound books containing all TSBs issued in 1996. Upon receipt, discard all 1996 bulletins and refer only to the bound book for reference.
• Additional copies of 1994 through 1997 TSBs are available to all Toyota dealerships through the Toyota Non-Parts System (MDC NPM System) by using the following Part Number designation:



Parts Information

Table with 2 columns: MATERIAL DESCRIPTION, PART NUMBER. Rows include: 1997 TSB Binder complete with all bulletins issued to date (TSB97), New TSB Binder and tabs ONLY (00406-61012), 1996 TSB Bound Book (00442-97003*), 1995 TSB Bound Book (00401-43055), 1994 TSB Bound Book (00401-43037).

* Available in March, 1997.

NOTE:

If you have any questions concerning Toyota Technical Service Bulletins, please contact your District Service Manager.

