



Technical Service BULLETIN

March 6, 1998

Title:

1998 TECHNICAL SERVICE BULLETIN INFORMATION


Models:

All Models

PRODUCT GENERAL INFORMATION
PG002-98

Introduction Toyota Technical Service Bulletins (TSBs) continue to be one of the most current sources of technical information available. To ensure complete access to this reference source, use the following steps:

- All 1997 Technical Service Bulletins should be relocated to a temporary binder.
- Place this bulletin along with all 1998 TSBs into the emptied TSB binder.
- During the month of March, all dealers will receive bound books containing all TSBs issued in 1997. Upon receipt, discard all 1997 TSBs and refer only to the bound book for reference.
- Additional copies of 1994 through 1998 TSBs are available to all Toyota dealerships through the Toyota Non-Parts System (MDC NPM System) by using the following Part Number designation:



Parts Information

MATERIAL DESCRIPTION	PART NUMBER
1998 TSB Binder complete with all bulletins issued to date	TSB98
New TSB Binder and tabs ONLY	00406-61012
1997 TSB Bound Book	00442-97011*
1996 TSB Bound Book	00442-97003
1995 TSB Bound Book	00401-43055
1994 TSB Bound Book	00401-43037

* Available in March, 1998.

NOTE:

If you have any questions concerning Toyota Technical Service Bulletins, please contact your District Service Manager.

