



**Technical Service  
BULLETIN**  
January 26, 2001

Title:  
**2001 TECHNICAL SERVICE BULLETIN  
INFORMATION**


Models:  
**All Models**

PG002-01

PRODUCT GENERAL INFORMATION

**Introduction** Toyota Technical Service Bulletins (TSBs) continue to be one of the most current sources of technical information available. To ensure complete access to this reference source, use the following steps:

- ☐ All 2000 Technical Service Bulletins should be relocated to a temporary binder.
- ☐ Place this bulletin along with all 2001 TSBs into the emptied TSB binder.
- ☐ During the month of March, all dealers will receive bound books containing all TSBs issued in 2000. Upon receipt, discard all 2000 TSBs and refer only to the bound book for reference.
- ☐ Additional copies of 1994 through 2001 TSBs are available to all Toyota dealerships through the Toyota Non-Parts System (MDC NPM System) by using the following Part Number designation:



**Parts  
Information**

MATERIAL DESCRIPTION	PART NUMBER
TSB Binder, tabs and all 2001 bulletins issued to date	TSB01
New TSB Binder and tabs <b>ONLY</b>	00406-61012
2000 TSB Bound Book	00442-01001*
1999 TSB Bound Book	00442-99002
1998 TSB Bound Book	00442-98005
1997 TSB Bound Book	00442-97011
1996 TSB Bound Book	00442-97003

\* Available in March, 2001.

**NOTE:**  
If you have any questions concerning Toyota Technical Service Bulletins, please contact your District Service Manager.

