



**Technical Service  
BULLETIN**

March 13, 1998

Title:

**A/C INDICATOR LIGHT OPERATION IN  
DEFROSTER MODE**

Models:

'98 Tacoma, '98 T-100, '98 4Runner, '98 Tercel

HEATING & AIR CONDITIONING  
AC001-98

**Introduction** For the 1998 model year, the operation of the A/C indicator light has been changed. With the A/C switch **OFF**, when the defroster mode is selected, the A/C indicator light does **NOT** turn **ON** even though the A/C compressor is in operation.

MODEL	A/C LIGHT STATUS IN DEFROST		IMPLEMENTATION
	A/C SWITCH OFF	A/C SWITCH ON	
Tacoma	<b>OFF</b>	<b>ON</b>	from 1998 model year
T-100	<b>OFF</b>	<b>ON</b>	from 1998 model year
4Runner	<b>OFF</b>	<b>ON</b>	from 1998 model year
Tercel	<b>OFF</b>	<b>ON</b>	from 1998 model year* <sup>1</sup>

\*<sup>1</sup> Tercel only: from December 1997

**Affected  
Vehicles**

- **1998** model year **Tacoma, T-100, 4Runner** and **Tercel**.

**Warranty  
Information**

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-

