

Power System Initialization During PDS

Service Category General

Section Pre-Delivery Service

Market USA

Toyota Supports
 ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2008	4Runner, Avalon, Camry, Camry HV, Corolla, FJ Cruiser, Highlander, Highlander HV, Land Cruiser, Matrix, Prius, RAV4, Sequoia, Sienna, Solara, Tacoma, Tundra	

Introduction

The following is a list of the vehicle systems (Power Window, Sliding Roof, Tire Pressure Warning System [TPWS], etc.) that need initialization during Pre-Delivery Service (PDS) and the TSB numbers containing details on initializing each specific system.

NOTE

Items in **RED** also need to be initialized any time the battery has been disconnected.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
N/A	Not Applicable to Warranty	—	—	—	—

Power System Initialization During PDS

Power System Initialization

MODEL NAME	INITIALIZATION SYSTEM ITEMS						
	BACK DOOR POWER WINDOW	COMPASS	POWER WINDOW	POWER BACK DOOR	POWER SLIDING DOOR	SLIDING ROOF	DIRECT TPWS
4Runner	PD061-07	PD059-07	PD062-07	—	—	PD062-07	PD064-07
Avalon	—	PD086-07	PD080-07	—	—	PD102-07	PD082-07
Camry	—	PD052-07	—	—	—	—	PD067-07
Camry HV	—	PD071-07	—	—	—	—	PD068-07
Corolla	—	PD027-07	—	—	—	—	PD033-07
FJ Cruiser	—	PD063-07	—	—	—	—	PD092-07
Highlander	—	PD015-07	—	—	—	—	PD022-07
Highlander HV	—	PD126-07	—	—	—	—	PD133-07
Land Cruiser	—	—	—	—	—	—	PD134-07
Matrix	—	PD036-07	—	—	—	—	PD032-07
Prius	—	—	PD004-07	—	—	—	PD105-07
RAV4	—	—	—	—	—	—	PD116-07
Sequoia	—	PD146-07	—	—	—	—	PD150-07
Sienna	—	PD076-07	PD077-07	PD074-07	PD075-07	PD110-07	PD083-07
Solara	—	PD046-07	PD044-07	—	—	PD043-07	PD045-07
Tacoma	—	PD079-07	—	—	—	—	PD084-07
Tundra	—	PD141-07	—	—	—	—	PD142-07