



**Technical Service  
BULLETIN**  
December 28, 2001

Title:  
**REPAIR MANUAL CORRECTIONS INDEX**  
Models:  
**All Models**



REVISED

PG003-01

PRODUCT GENERAL INFORMATION

**Introduction** Corrections have been made in the repair manuals listed below. Corrections available in the last quarter are marked in **red**, and have already been mailed to all dealers.

**NOTE:**  
When ordering a technical publication (i.e. Repair Manual, Electrical Wiring Diagram) from the MDC, any Correction Page(s) associated with that particular Publication will automatically be included with your order.

**Parts Information** Correction Pages are available through the Dealer Support Material Network (MDC NPM System) via the corresponding part numbers from the following table:

	Publication	Number	Page(s)	Part Number
<b>Avalon</b>	2000 Avalon .....	RM746-U1 .....	DI-449 .....	00400-RM746-1008
	.....	.....	DI-466 .....	↓
	.....	.....	SS-33 .....	00400-RM746-1085A
	.....	RM746-U2 .....	SR-11 .....	00400-RM746-1085B
	.....	.....	SR-21 .....	↓
	2001 Avalon .....	RM808-U1 .....	SS-33 .....	00400-RM808-1085A
	.....	RM808-U2 .....	SR-11 .....	00400-RM808-1085B
	.....	.....	SR-21 .....	↓
	2002 Avalon .....	RM872-U1 .....	SS-33 .....	00400-RM872-1085A
	.....	RM872-U2 .....	SR-11 .....	00400-RM872-1085B
	.....	.....	SR-21 .....	↓
	<b>Camry</b>	2000 Camry .....	RM742-U1 .....	DI-723 .....
2002 Camry .....		RM836-U .....	40-60 .....	00400-RM836-1122
.....		RM840-U .....	40-57 .....	00400-RM840-1123
.....		RM881-U2 .....	32-16 .....	00400-RM881-1137B
.....		.....	73-22-1 .....	00400-RM881-1152B
.....		EWD46-1U .....	186 .....	00400-EWD46-11169
.....		.....	187 .....	↓
.....		.....	230 .....	↓
.....		.....	16-5 .....	↓
.....		.....	17-1 .....	↓



	<b>Publication</b>	<b>Number</b>	<b>Page(s)</b>	<b>Part Number</b>
<b>Celica</b>	2000 Celica .....	RM735-U .....	PP-1 .....	00400-RM735-1047
	.....	.....	PP-2 .....	↓
	.....	.....	PP-3 .....	↓
	.....	.....	PP-4 .....	↓
	.....	.....	AX-13 .....	↓
	.....	.....	AX-18 .....	↓
	.....	.....	AX-20 .....	↓
	.....	.....	AX-25 .....	↓
	.....	.....	AX-30 .....	↓
	.....	.....	AX-58 .....	↓
	.....	.....	AX-61 .....	↓
	.....	.....	AX-64 .....	↓
	.....	.....	AX-66 .....	↓
	.....	RM740-U .....	AX-52 .....	00400-RM740-1118
	.....	RM744-U1 .....	DI-427 .....	00400-RM744-1005
	.....	.....	SS-34 .....	00400-RM744-1011A
	.....	.....	SS-35 .....	↓
	.....	.....	SS-39 .....	↓
	.....	.....	SS-40 .....	↓
	.....	RM744-U2 .....	MX-3 (C56) .....	00400-RM744-1011B
	.....	.....	MX-5 (C56) .....	↓
	.....	.....	MX-6 (C56) .....	↓
	.....	.....	MX-7 (C56) .....	↓
	.....	.....	MX-7-1 (C56) .....	↓
	.....	.....	MX-8 (C56) .....	00400-RM744-1011B
	.....	.....	MX-3 (C60) .....	↓
	.....	.....	MX-5 (C60) .....	↓
	.....	.....	MX-6 (C60) .....	↓
	.....	.....	MX-7 (C60) .....	↓
	.....	.....	MX-7-1 (C60) .....	↓
	.....	.....	MX-8 (C60) .....	↓
	.....	.....	CL-14 .....	00400-RM744-1043B
	.....	.....	CL-16 .....	↓
.....	.....	CL-16-1 .....	↓	
2001 Celica .....	RM818-U2 .....	CL-14 .....	00400-RM818-1044B	
.....	.....	CL-16 .....	↓	
.....	.....	CL-16-1 .....	↓	
.....	.....	SS-34 (C56) .....	00400-RM818-1012B	
.....	.....	SS-35 (C56) .....	↓	
.....	.....	MX-3 (C56) .....	↓	
.....	.....	MX-5 (C56) .....	↓	
.....	.....	MX-6 (C56) .....	↓	
.....	.....	MX-7 (C56) .....	↓	
.....	.....	MX-7-1 (C56) .....	↓	

	<b>Publication</b>	<b>Number</b>	<b>Page(s)</b>	<b>Part Number</b>
<b>Celica</b> (Continued)	2001 Celica .....	RM818-U2 .....	MX-8 (C56) .....	00400-RM818-1012B
	.....	.....	MX-3 (C60) .....	↓
	.....	.....	MX-5 (C60) .....	↓
	.....	.....	MX-6 (C60) .....	↓
	.....	.....	MX-7 (C60) .....	↓
	.....	.....	MX-7-1 (C60) .....	↓
	.....	.....	MX-8 (C60) .....	↓
	.....	.....	SS-39 (C60) .....	↓
	.....	.....	SS-40 (C60) .....	↓
<b>Corolla</b>	2000 Corolla .....	RM719-U .....	DI-265 .....	00400-RM719-1009
	.....	.....	DI-334 .....	↓
<b>ECHO</b>	2000 ECHO .....	RM735-U .....	PP-1 .....	00400-RM735-1047
	.....	.....	PP-2 .....	↓
	.....	.....	PP-3 .....	↓
	.....	.....	PP-4 .....	↓
	.....	.....	AX-13 .....	↓
	.....	.....	AX-18 .....	↓
	.....	.....	AX-20 .....	↓
	.....	.....	AX-25 .....	↓
	.....	.....	AX-30 .....	↓
	.....	.....	AX-58 .....	↓
	.....	.....	AX-61 .....	↓
	.....	.....	AX-64 .....	↓
	.....	.....	AX-66 .....	↓
	<b>Highlander</b>	2001 Highlander .....	RM837-U2 .....	73 INDEX .....
.....		.....	73-16 – 73-23 .....	↓
.....		.....	72-1 .....	00400-RM837-1040B
.....		.....	72-2 .....	↓
.....		.....	72-5 .....	↓
.....		.....	72-6 .....	↓
.....		.....	72-7 .....	↓
.....		.....	76-5 .....	00400-RM837-1083B
.....		.....	76-5-1 .....	↓
.....		.....	73-11 .....	↓
.....		.....	73-12 .....	↓
.....		.....	73-13 .....	↓
.....		RM836-U .....	40-60 .....	00400-RM836-1122
.....		RM840-U .....	40-57 .....	00400-RM840-1123
.....	EWD44-2U .....	29 .....	00400-EWD44-21025	

	<b>Publication</b>	<b>Number</b>	<b>Page(s)</b>	<b>Part Number</b>
<b>Land Cruiser</b>	1999 Land Cruiser .....	RM661-U1 .....	SS-25 .....	00400-RM661-1034A
	.....	RM661-U2 .....	TR-32 .....	00400-RM661-1034B
	2000 Land Cruiser .....	RM722-U1 .....	DI-516 .....	00400-RM722-1010
	.....	.....	SS-25 .....	00400-RM722-1034A
	.....	.....	SS-30 .....	00400-RM722-Z154A
	.....	RM722-U2 .....	SA-3 .....	00400-RM722-Z154B
	.....	.....	TR-32 .....	00400-RM722-1034B
	2001 Land Cruiser .....	RM795-U1 .....	SS-25 .....	00400-RM795-1034A
	.....	.....	SS-30 .....	00400-RM795-Z154A
	.....	RM795-U2 .....	SA-3 .....	00400-RM795-Z154B
	.....	.....	TR-32 .....	00400-RM795-1034B
	<b>MR2 Spyder</b>	<b>2000 MR2 .....</b>	<b>RM760-U .....</b>	<b>BR-17 .....</b>
<b>Prius</b>	2001 Prius .....	RM778-U1 .....	DI-330 .....	00400-RM778-1035A
	.....	.....	DI-330-1 .....	↓
	.....	.....	DI-340 .....	↓
	.....	.....	DI-340-1 .....	↓
	.....	.....	DI-340-2 .....	↓
	.....	.....	DI-341 .....	↓
	.....	.....	DI-342 .....	↓
	.....	.....	DI-342-1 .....	↓
	.....	.....	DI-342-2 .....	↓
	.....	.....	DI-477 .....	00400-RM778-Z157A
	.....	.....	DI-478 .....	↓
	.....	.....	DI-480 .....	00400-RM778-1052A
	.....	RM778-U2 .....	SR-17 .....	00400-RM778-Z157B
	.....	.....	SR-25 .....	↓
	.....	.....	SR-26 .....	↓
	.....	.....	HV-10 .....	00400-RM778-1021B
	.....	.....	HV-11 .....	↓
<b>RAV4</b>	<b>2000 RAV4 .....</b>	<b>RM772-U .....</b>	<b>AX-45 .....</b>	<b>00400-RM772-1120</b>
	<b>2001 RAV4 .....</b>	<b>RM815-U .....</b>	<b>AX-52 .....</b>	<b>00400-RM815-1121</b>
	<b>.....</b>	<b>RM797-U2 .....</b>	<b>BR-21 .....</b>	<b>00400-RM797-1142B</b>
<b>Sequoia</b>	2001 Sequoia .....	RM832-U1 .....	DI-231 .....	00400-RM832-Z156A
	.....	.....	DI-232 .....	↓
	.....	.....	DI-233 .....	↓
	.....	.....	DI-240 .....	↓
	.....	.....	DI-241 .....	↓

	<b>Publication</b>	<b>Number</b>	<b>Page(s)</b>	<b>Part Number</b>
<b>Sequoia</b> (Continued)	2001 Sequoia	RM832-U1	BR-51	00400-RM832-1014
			DI-232	00400-RM832-1019
		RM832-U2	AC-102	00400-RM832-1065B
			AC-105	↓
			AC-107	↓
			AC-108	↓
			SA-4	00400-RM832-Z156B
			SA-15	↓
			SA-62	↓
			SA-68	↓
			SA-77	↓
			BR-20	↓
			BR-54	↓
			SR-1	↓
			SR-23	↓
			SR-54	↓
			SS-41	00400-RM832-1014
			BR-50	↓
			TR-49	00400-RM832-1064B
	<hr/>			
<b>Sienna</b>	2000 Sienna	RM701-U1	DI-322	00400-RM701-1007
<hr/>				
<b>Solara</b>	2000 Solara	RM713-U1	DI-575	00400-RM713-1004
			DI-644	↓
<hr/>				
<b>Tacoma</b>	2000 Tacoma	EWD38-5U	42	00400-EWD38-51041
			43	↓
			173	↓
			198	↓
			202	↓
	2001 Tacoma	RM835-U1	SS-65	00400-RM835-Z153
			SS-66	↓
			SS-67	↓
			SS-68	↓
			SS-69	↓
			SS-70	↓
	2002 Tacoma	RM921-U1	DI-367	00400-RM921-1155
			DI-369	↓
			DI-402	↓