



**Technical Service
BULLETIN**

January 19, 2008

Title:

**REPAIR MANUAL SUPPLEMENT:
VEHICLE PULLING TO ONE SIDE**

Models:

'08 Toyota

SUSPENSION
SU001-08

TSB OBSOLETE NOTICE:

December 24, 2008: This TSB is now obsolete.

Please see T-SB-0391-08.

