



TECHNICAL SERVICE BULLETIN

REF.: PRODUCT GENERAL
INFORMATION
NO.: PG93-002
DATE: EFFECTIVE
APRIL 09, 1993
MODEL: ALL MODELS

VIN PLATES & CERTIFICATION LABELS

Page 1 of 2

Replacement VIN plates (riveted to dashboard) and Certification Labels (affixed to driver's door or door post) are available from Toyota providing the request meets one of the following criteria:

- The original label is incorrect (an incorrect Certification Label must accompany the request; an incorrect VIN plate must be returned after receipt of the new one).
- The vehicle is in an accident and the plate or label is damaged or is attached to a part that will be replaced during the repair* (the plate or label to be replaced must accompany the request).
- The plate or label is stolen*. Be sure to contact State Police or the Department of Motor Vehicles; in many cases they will issue a unique number so that the original can be included on stolen vehicle listings. When requesting a new plate or label to replace a stolen one, it is necessary to include a copy of the police or insurance company report.

* *All replacement plates and labels for damaged and/or stolen vehicles are subject to approval by the Technical Compliance Department. If you have any specific questions, contact (310) 781-3390.*

Aluminum Certification Plates are no longer available as replacements. If one is requested, a vinyl label containing information from this plate combined with information from the manufacturer's plate (mounted on the engine compartment side of the cowl panel) will be supplied instead.

To request a replacement plate or label, complete the appropriate portion of the form on the second page. Note that damaged VIN plates or labels must accompany the request form. Your dealer parts account will be billed \$10.00 for each replacement of a damaged plate or label. Replacements for incorrect plates or labels will be provided free of charge.

MAIL THE COMPLETED REQUEST FORM WITH THE REQUIRED ENCLOSURE TO:

TOYOTA MOTOR SALES, U.S.A., INC.
TECHNICAL COMPLIANCE DEPT. S203
19001 S. WESTERN AVENUE
TORRANCE, CA 90509-2991

TOYOTA MOTOR SALES U.S.A., INC.



APPLICATION FOR REPLACEMENT CERTIFICATION LABELS OR VIN PLATES

DEALER INFORMATION

Complete this section or your order can NOT be processed!

Dealer Code:

Dealer Name:

Address:

City, State, Zip:

Contact Person:

Telephone #:

REPLACEMENT CERTIFICATION LABEL

Complete this section ONLY if you need a CERTIFICATION LABEL.

REASON FOR REPLACEMENT:

LABEL INCORRECT*

ACCIDENT DAMAGE

STOLEN

(Allow extra time to process)

*Provide correct VIN

**AFFIX ORIGINAL LABEL HERE
OR ATTACH TO THIS FORM**

NOTE: ORIGINAL LABEL **MUST** ACCOMPANY THIS
APPLICATION OR THE ORDER CAN NOT BE
PROCESSED!

REPLACEMENT VIN PLATE

Complete this section ONLY if you need a VIN PLATE.

VIN PLATE INCORRECT

Provide **INCORRECT** and **CORRECT** VIN information

INCORRECT VIN:

CORRECT VIN:

INCORRECT VIN plate MUST be returned after receipt of new VIN plate!!

VIN PLATE DAMAGED

Damaged VIN plate **MUST** accompany this application