

TOYOTA

SERVICE BULLETIN

TOYOTA MOTOR SALES, U.S.A., INC.

VOLUME


10

REFERENCE BODY
NUMBER 018
DATE 05-05-89
MODEL FJ6#

Page 1 of 1

WINDSHIELD WIPER LINKAGE RODS

To improve the serviceability of the windshield wiper linkage assembly, the two rods in the wiper linkage are now available as separate replacement parts (see illustration).



Note: The rod does not include the pivot.

PART NUMBER INFORMATION:

PART NAME	PREVIOUS P/N	NEW P/N
Link assembly, wiper	85160-90A07	← SAME
Rod, wiper link 1	N/A	85164-90A02
Rod, wiper link 2	N/A	85165-90A01

Note:

Rod, wiper link 1; connected from wiper motor to pivot.
Rod, wiper link 2; connected between two pivots.

INTERCHANGEABILITY:

New and previous parts are completely interchangeable.