

TOYOTA

SERVICE BULLETIN

TOYOTA MOTOR SALES, U.S.A., INC.

VOLUME

9

REFERENCE BRAKES
NUMBER 004
DATE 12-11-87
MODEL MX73

DISC BRAKE PADS - BRAKE NOISE

To minimize brake squeak and groan noise, the pad material was changed during April, 1987 production.

Production Effective

<u>VIN</u>	<u>Production Date</u>
JT2MX73##H0129480	April, 1987

Part Number Information

<u>Previous Part Number</u>	<u>New Part Number</u>	<u>Part Name</u>
04491-22173	04491-22250	Pad kit, front
04492-22042	04492-22043	Pad kit, rear

Previous Vehicle Part Number Information

<u>Production Date</u>	<u>Previous Part No.</u>	<u>New Part Number</u>	<u>Part Name</u>
8/85 to 1/87	04491-22172	04491-22250	Pad kit, front
*1/87 to 4/87	04491-22173	04491-22250	Pad kit, front
8/85 to 1/87	04492-22040	04492-22043	Pad kit, rear
*1/87 to 4/87	04492-22042	04492-22043	Pad kit, rear

Note: * When working on vehicles built between 1/87 to 4/87, both front and rear pad kits must be replaced with the new part numbers. Do not mix old and new parts front to rear.