



**Technical Service
BULLETIN**

March 29, 2005

Title:

**NO PICTURE DISPLAYED FROM
BACKUP CAMERA**

Models:

'04 4Runner & Sienna

**ELECTRICAL
EL003-05**

Introduction Some customers may experience a blank screen when shifting into reverse on vehicles equipped with the Toyota Navigation System and backup camera. An improved camera has been developed to remedy this condition.

- Applicable Vehicles**
- **2004** model year **4Runner** and **Sienna** vehicles **equipped with the Toyota Navigation System** produced **BEFORE** the Production Change Effective VINs shown below.

Production Change Information

MODEL	PLANT	VDS	PRODUCTION CHANGE EFFECTIVE VIN
4Runner	Tahara	ZU14R	JTEZU14R*40023247
		BU14R	JTEBU14R*40027918
		ZT14R	JTEZT14R*40015261
		BT14R	JTEBT14R*40031466
	Hino	ZU14R	JTEZU14R*48013072
		BU14R	JTEBU14R*48015773
		ZT14R	JTEZT14R*48003535
		BT14R	JTEBT14R*48018597
Sienna	TMMI	ZA22C	5TDZA22C*4S055073
		BA22C	5TDBA22C*4S011293

Parts Information

MODEL	PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
4Runner	86790-35010	Same	Camera Assembly, Television	1
Sienna	86790-45010			

Repair Procedure

Replace the backup camera. Refer to the Technical Information System (TIS): 2004 model year 4Runner or Sienna Repair Manual: *Audio & Visual System: Television Camera Assy: Replacement.*

Warranty Information

OP CODE	DESCRIPTION	MODEL	TIME	OFFP	T1	T2
EL5050	R & R Camera Assembly, Television	4Runner	0.4	86790-35010	72	71
		Sienna	0.4	86790-45010		

Applicable Warranty*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

