



**Technical Service
BULLETIN**

December 18, 2002

Title:


**PRECAUTION FOR UPPER CONSOLE
BOX REMOVAL AND INSTALLATION**

Models:

'03 4Runner

BODY
B0021-02

Introduction When removing or installing the upper console box on the 2003 model year 4Runner, ensure the door is open to prevent interference with the upper console panel.



**Applicable
Vehicles**

- 2003 model year 4Runner vehicles.

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-

